



Passive System Rehabilitation of a High Flow Acidic Coal Mine Discharge

Presenter: Ryan M. Mahony

Additional Authors: T.P. Danehy, D.A. Guy, C.F. Denholm, S.L. Busler, C.A. Neely, M.H. Dunn

Site Location




Image credit: maps.google.com

Maiden Passive Treatment System Background


- ▶ Constructed 2006 to treat an abandoned acidic coal mine discharge
- ▶ Largest passive system in Dunkard Creek Watershed
- ▶ Treats 2 mine discharges




Reference: www.datashed.org

Maiden Passive Treatment System Background

- ▶ High flow/loading discharge with no maintenance for almost 10 years due to refusal of landowner access from 2006 through 2015
- ▶ Land purchase by MEPCO, LLC in 2015
- ▶ Maintenance Aug-Nov 2016





SITE SCHEMATIC
MATHIEWS
 RESTORATION AREA
 DUNKARD CREEK WATERSHED
 Dunkard Twp., Greene Co., PA
 December 2007 Scale: 1" = 200'
 Biomst, Inc.
 www.biomst.com

Raw Water Quality Data (Avg)

Sample Point	Flow (gpm)	pH	Acidity (mg/L)	Fe (mg/L)	Mn (mg/L)	Al (mg/L)
117-6A	28.5	2.8	359	26	3.5	28
117-1	321	2.7	354	46	4.2	19

*Each discharge treated by separate set of components within the "system"

Site Challenges

- ▶ Flooding of state route due to beaver activity at outlet of system
- ▶ HFLB clogged and overgrown with vegetation
- ▶ VFP1, VFP2B, & VFP3 siphons not functional
- ▶ VFP1, VFP2B, VFP3 stone clogged with Fe precipitates
- ▶ SP1/ Oxidation precipitation channel overflowing
- ▶ No flow to VFP2A (clogged inlet pipe)
- ▶ Underdrain pipes clogged in multiple components

Beaver Issues



- ▶ Left: Beaver dam at outlet of oxbow lake located at the system outlet
- ▶ Right: Flooding due to beaver dam on state road (August 2015)

Beaver Issues



- ▶ Installed dual 24" piping as "beaver proof" system outlet

HFLB Overgrown & Clogged



HFLB Maintenance




- ▶ HFLB upgraded with infiltration trenches & inlet/outlet pools

VFP2B Siphon Repair



- ▶ Siphon trigger damaged by wildlife

VFP2B Siphon Repair



VFP2B Siphon Repair




VFP3 Siphon Repair



- ▶ Damaged siphon bell was retrofitted with improved bracing

VFP1 Siphon Replacement



- ▶ Solar powered mechanically actuated valve installed to drain VFP1 on set schedule

VFP1 Media Clogged



- ▶ Media was clogged in VFP1 causing all raw water to short circuit pond

VFP1 Media Cleaning



- ▶ Iron precipitates had completely filled void space within the pond

VFP1 Media Cleaning



- ▶ Excavator and 3" pump with 2" firehose attachment used to wash stone

VFP1 Underdrain Replacement



- ▶ Perforated 8" HDPE pipe with caps used to create more durable underdrain


VFP3 Media Clogged



- ▶ All flow bypassed treatment through emergency spillway

VFP3 Media Cleaning

- ▶ Limestone was cleaned and underdrain was repaired and kept in place



Channel Retrofit



- ▶ VFP2A & VFP2B "combined" with VFP2B as "high flow use only" component

VFP2A Offline



- ▶ System component offline for almost 10 years with no treatment

VFP2A Stirred



- ▶ Media was "fluffed" to improve permeability

VFP2A Adjustments



- ▶ VFP2A outlet risers were adjusted due to variable site conditions and effluent quality goals

VFP2A Stirred (Again)



- ▶ High quality treatment from media but less than expected flow prompted a second media stir

VFP2B Stirred



- ▶ Media stirred, HDPE underdrain installed, infiltration trench installed

General Maintenance



Settling pond 8" bypass valve replacement and removal of E&S controls left in place from initial system construction

Post Maintenance Water Quality

Sample Point	Flow (GPM)	pH (field)	Acidity (mg/L)	Alkalinity (mg/L)	Fe (mg/L)	Mn (mg/L)	Al (mg/L)
117-1 (Avg) n=32	321	2.88	354	NM	46	4	19
Effluent (post rehab avg) n=6	327	5.2	54.9	36	1.3	1.6	5.6

*Note 3/5/2017 sampling was a flow of 689 gpm, pH 3.52, acidity 124 (over double system design flow) and is included in effluent average

*Data available at www.datashed.org

Project Accomplishments

- ▶ Cleaned 10,500 tons of limestone (VFP1, VFP2B, VFP3, HFLB)
- ▶ Installed 600 feet of HDPE underdrain pipe (VFP1 & VFP2B)
- ▶ Rehabilitated 1,300 CY of treatment media (VFP2A)
- ▶ Installed 150' -long channel to by-pass clogged culvert
- ▶ Installed flow-balancing channel between VFP2A & VFP2B
- ▶ Installed pipe outlet control on VFP2B
- ▶ Repaired VFP2B siphon mechanism that was damaged by wildlife
- ▶ Repaired VFP3 siphon worn by almost a decade of use
- ▶ Installed dual 24" piping as "beaver proof" system outlet
- ▶ Replaced 8" by-pass valve (SP1)
- ▶ Reconfigured HFLB to include inlet and outlet pools and infiltration trenches
- ▶ Installed solar powered valve actuator at VFP1

What Next?

- ▶ Plans to retrofit VFP2B as a mixed media component
- ▶ Continued stirring of limestone to maintain media permeability
- ▶ Install perforated riser pipe at HFLB outlet

Project Partners

- ▶ Foundation for Pennsylvania Watersheds
- ▶ Appalachian Stewardship Fund
- ▶ Western PA Coalition for Abandoned Mine Reclamation/PADEP
- ▶ SRI Operation & Maintenance Technical Assistance Grant (Growing Greener Funded)
- ▶ AMDRI
- ▶ MEPCO, LLC (property acquisition for site access + on-going water monitoring as part of AMDRI Dunkard Creek Watershed Management Plan)
- ▶ Stream Restoration Incorporated
- ▶ BioMost, Inc.

Questions?

