# **Geomorphic Reclamation of Abandoned Coal Mines near Raton, NM**



#### The Swastika Mine and Dutchman Canyon Reclamation Project

Design and Construction Oversight



Completed
Geomorphic
Reclamation of
Dillon Canyon
at the Swastika
Abandoned
Coal Mine Site

Sept. 18, 2012


# **Geomorphic Reclamation of Abandoned Coal Mines near Raton, NM**



#### The Swastika Mine and Dutchman Canyon Reclamation Project

- Design and Construction Oversight
- Reclamation and Revegetation







# **Geomorphic Reclamation of Abandoned Coal Mines near Raton, NM**



Presented By: Kate Malers, P.E.: Water & Earth Technologies (WET)

**Additional Preparers:** 

Richard Spotts, P.E. (WET)
Melissa Brennan, P.E. (WET)
Ryan Wade, P.E. (WET)

Ken Carlson: Habitat Management, Inc. (HMI)




**Zoe Isaacson: New Mexico Abandoned Mine Land Program (NM AMLP)** 




# Historic Mining in the Raton Coal Field near Raton, NM

Swastika Mine, 1917-1953








#### Abandoned Mines in Dillon Canyon



#### **Abandoned Coal Waste at Swastika Mine**







#### **Environmental Detriments Associated with Abandoned Coal Waste**



- Unstable coal waste slopes collapsing into the stream
- Infiltration leaching contaminants from the coal waste pile and conveying them to the stream channel
- Coal waste eroding into the stream during runoff events

#### **Environmental Detriments Associated with Abandoned Coal Waste**

In those locations where runoff from the mountainside above the waste pile crossed the pile, very deep gullies eroded through the coal waste.



#### **Environmental Detriments Associated with Abandoned Coal Waste**


The "Dillon Canyon Stream" is an emphemeral tributary, with scattered perennial pools.





#### **Environmental Detriments Associated with Stream Channelization**

- The stream was straightened to accommodate coal handling facilities
- Channelization reduces stream gradient and increases flow velocities
- High flow velocities erode the channel bed and banks, destabilizing the stream



#### **Environmental Detriments Associated with Stream Channelization**

- Channel bed degradation propagates from the disturbed reach
- Bank erosion works towards the return to a meandering stream alignment
- However, bank erosion is undesirable because it undercuts the coal waste pile and the road



#### **Environmental Detriments Associated with Stream Channelization**

The large capacity channel conveys flood flows inchannel, without the benefits of floodplain inundation:

- Zones of shallow, slow overbank flood flow and deposition
- Bank storage
- Flood peak attentuation
- Riparian habitat benefits



# Traditional Reclamation on Vermejo Park Ranch


Koehler Mine near Raton, NM






- Terraced Landforms with Downdrains
- Channels Armored with Rip Rap

# **Geomorphic Design**: Mimic Stable Natural Stream and Landform Characteristics Created by Natural Processes



Undisturbed Reach of Dillon Canyon

- Reduce Maintenance
- Improve Aesthetic and Habitat Values



Geomorphic Design

#### **Design Challenges**



- Determining the design volume of coal waste to be reclaimed, given uncertainties about the underlying "native" landform obscured by the pile
- Determining appropriate slopes and slope lengths for reclaimed landforms that will have no underlying geologic structure


### **Design Challenges**



- Conveying runoff from the undisturbed hillside across the reclaimed landform and into the channel
- Preserving a row of archaeological features lying at the base of the hillside behind the bench of coal waste.




### **Design Challenges**



- Scattered archaeological features
- Power poles (during the design phase), and power lines (during construction)
- Scattered resources including mature trees and wetlands

#### **Project Approach: Stream and Road Realignment**

- Reshape the coal waste "bench" into a landform with stable slopes
- Return the channel to a restored, meandering alignment in the center of the valley
- Return the road to the abandoned road alignment on the east side of the valley, with road and drainage improvements



### **Project Approach: Partial Removal of Coal Waste**

Remove enough material to accommodate the remaining coal waste volume in geomorphic landforms with stable slopes



# Project Approach: Combination Soil Borrow/Coal Waste Repository Landforms



- Provide borrow soil for capping coal waste landforms
- •Provide excavated volume and additional volume above the natural ground surface for backfill by coal waste
- Minimize disturbance area

#### **Combination Soil Borrow/Coal Waste Repository Landforms**



### **Combination Soil Borrow/Coal Waste Repository Landforms**



South
Combination
Soil
Borrow/Coal
Waste
Repository
with wood
straw mulch

May 3, 2013

### **Completed Geomorphic Landform at Pile 3**



Geomorphic Landform and Integrated Drainage Channel

March 7, 2013


# **GPS Machine-Control Landform Construction**







### Plan View of Project Cut/Fill Balance



- Preventing Disturbance to Archaeological and other Avoidance Zones
- Cut/Fill Balance for Coal Waste, Clean Fill and Capping Soil
- Minimizing Double- and Triple-Handling of Materials while Minimizing Disturbance Area

#### Dillon Canyon Coal Waste Landforms Before, During, After Geomorphic Reshaping







Dillon Canyon Stream Channel Before, During, and After Geomorphic Realignment and Restoration








#### **Template Stream Reaches**



Template Reach of Dillon Canyon

- Low gradient, sinuous channel
- Low flow channel armored with small rocks
- Wide, shallow channel cross section with moderate, vegetated banks
- High flows inundate a functional, vegetated floodplain with shallow, low velocity flow

#### **Geomorphic Channel Realignment and Restoration**



Note: Cross sections are drawn from left to right looking down the channel centerline in the direction of increasing stationing.

Typical channel cross section geometry, transitioning from steeper to flatter side slopes depending upon the location in the meander pattern



Steeper slopes on the outside of meanders are protected with a heavier TRM product (green) in the completed restoration

### **Geomorphic Channel Realignment and Restoration**

A berm of clear (1) A bern of clear (1) A bern

Coal waste was exc within the "Meand channel as a precal exposure as the ch time



## **Geomorphic Channel Realignment and Restoration**



# **Reclaimed Valley**



### **Compatibility with Undisturbed Features of the Valley**

